

**GOVERNMENT OF TELANGANA**  
**ABSTRACT**

Public Servants – PR&RD Dept. – Allegations of irregularities in drawing of bill for construction of (18) PYKKA Buildings, District Sports Authority (DSA) Mahabubnagar against Sri P.I. Praveen Kumar, Assistant Engineer, Jadcherla presently working in MPP Dhawada, Mahabubnagar District - Disciplinary proceedings initiated under Rule 20 of Telangana Civil Services (Classification, Control & Appeal) Rules, 1991 – Article of charges – Issued.

-----  
PANCHAYAT RAJ & RURAL DEVELOPMENT (VIG.I) DEPARTMENT

**G.O.Rt.No. 499**

**Dated: 29-08-2019**

\*\*\*

**ORDER:**

It is proposed to hold an enquiry against Sri P.I. Praveen Kumar, Assistant Engineer, Jadcherla presently working in MPP Dhawada, Mahabubnagar District, in accordance with the procedure laid down in Rule 20 of the Telangana Civil Services (Classification, Control & Appeal) Rules, 1991.

2. The substance of the imputations of misconduct or misbehavior in respect of which the enquiry is proposed to be held is set out in the enclosed statement of article of charges (Annexure-I). A list of documents by which and a list of witnesses by whom, the article of charges are proposed to be sustained are also enclosed (Annexure-II&III).

3. Sri P.I. Praveen Kumar, Assistant Engineer, Jadcherla presently working in MPP Dhawada, Mahabubnagar District, is directed to submit his written statement of his defence within ten (10) days from the date of receipt of this order.

4. Sri P.I. Praveen Kumar, Assistant Engineer, Jadcherla presently working in MPP Dhawada, Mahabubnagar District, is informed that an enquiry will be held only in respect of article of those charges as are not admitted. He should, therefore, specifically admit or deny each article of charge.

5. Sri P.I. Praveen Kumar, Assistant Engineer, Jadcherla presently working in MPP Dhawada, Mahabubnagar District, is further informed that if he does not submit his written statement of defence on or before the Period specified in Para (3) above or otherwise fails or refuses to comply with the provisions of Rule 20 of Telangana Civil Services (Classification, Control & Appeal) Rules, 1991 or the orders / directions issued in pursuance of the said rules, the Inquiring Authority may hold the inquiry against him ex-parte.

6. Sri P.I. Praveen Kumar, Assistant Engineer, Jadcherla presently working in MPP Dhawada, Mahabubnagar District, is invited to Rule 24 of the Telangana Civil Services (Conduct) Rules, 1964, under which no Government Servant shall bring or attempt to bring any political or outside influence to bear upon any superior authority to further his interest in respect of matters pertaining to his service under the Government. If any representation is received on his behalf from another person in respect of any matter dealt within these proceedings, it will be presumed that Sri P.I. Praveen Kumar, Assistant Engineer, Jadcherla presently working in MPP Dhawada, Mahabubnagar District, is aware of such a representation and that it has been made at his instance and action will be taken against him for violation of Rule-24 of the Telangana Civil Services (Conduct) Rules, 1964.

7. The receipt of this G.O. shall be acknowledged.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)

VIKAS RAJ  
PRINCIPAL SECRETARY TO GOVERNMENT

To

Sri P.I. Praveen Kumar, Assistant Engineer, Jadcherla presently working in  
MPP Dhawada, Mahabubnagar District through the Engineer-in-Chief PR, Hyderabad  
The Engineer-in-Chief, PR, Hyderabad.

(in duplicate with a request to serve and return the dated acknowledgement copy)

(P.T.O)

::2::

Copy to:

The Secretary to VC, TVC, Hyderabad.

The Director General, General Administration (V&E) Department,  
BRKR Building, Hyderabad.

(w.r.t. Vigilance Report No.103 (298/V&E/EIII/2017, dt:27/10/2018)

SF/SC

//FORWARDED ::BY ORDER//

SECTION OFFICER

## **ANNEXURE –I**

(Annexure to G.O.Rt.No.499, PR&RD (Vig.I) Dept., dt.29.08.2019)

### **STATEMENT SHOWING THE ARTICLE OF CHARGES FRAMED AGAINST SRI P.I. PRAVEEN KUMAR, ASSISTANT ENGINEER, JADCHERLA PRESENTLY WORKING IN MPP DHAWADA, MAHABUBNAGAR DISTRICT.**

#### **CHARGE-I:-**

That Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district has executed the works of PYKKA buildings after the agreement period without valid permission.

#### **BASIS:**

The V&E Department made the following observations in their Vigilance Report No. 103 (298/V&E /E III/2017)/C.No.540/V&E/D2/2016), dt.27.10.2018 in respect of the works of C/O PYKKA Building at Sarjakhanpet, Chennaram, Mirjapur, Chendravanha and Togapur.

#### **Work No.1**

1	Name of the Work	C/o PYKKA Building at Sarjakhanpet,
2	Location of the work	Sarjakhanpet (V), Kosgi (M)
3	Estimate Cost Rs.in lakhs	1.00
4	Grant	PYKKA
5	Period provided in Agreement	3 months from the Date of Agreement 19.6.2012.
6	Date of completion of work as per original Agreement.	18.09.2012
7	Date of commencement of work/ Recording.	14.01.2013
8	Last Date of check measurement of work	04.03.2013

#### **Work No.2**

1	Name of the Work	C/o PYKKA Building at Chennaram
2	Location of the work	Chennaram (V), Kosgi (M)
3	Estimate Cost Rs. in lakhs	1.00
4	Grant	PYKKA
5	Period provided in Agreement	3 months from the Date of Agreement 31.07.2012.
6	Date of completion of work as per original Agreement.	30.10.2012
7	Date of commencement of work/ Recording.	Nil
8	Last Date of check measurement of work	04.05.2013

#### **Work No.3**

1	Name of the Work	C/o PYKKA Building at Mirjapur
2	Location of the work	Mirjapur (V), Kosgi (M)
3	Estimate Cost Rs.in lakhs	1.00
4	Grant	PYKKA
5	Period provided in Agreement	3 months from the Date of Agreement 14.09.2012
6	Date of completion of work as per original Agreement.	13.12.2012
7	Date of commencement of work/ Recording.	03.04.2013
8	Last Date of check measurement of work	09.08.2013

**(P.T.O)**

**::2::**

**Work No.4**

1	Name of the Work	C/o PYKKA Building at Chendravanha
2	Location of the work	Chendravanha (V), Kosgi (M)
3	Estimate Cost Rs.in lakhs	1.00
4	Grant	PYKKA
5	Period provided in Agreement	3 months from the Date of Agreement 03.08.2012.
6	Date of completion of work as per original Agreement.	02.11.2012
7	Date of commencement of work/ Recording.	20-11-2012
8	Last Date of check measurement of work	11.02.2013

**Work No.5**

1	Name of the Work	C/o PYKKA Building at Togapur
2	Location of the work	Togapur (v), Kosgi (M)
3	Estimate Cost Rs.in lakhs	1.00
4	Grant	PYKKA
5	Period provided in Agreement	3 months from the Date of Agreement 14.05.2012.
6	Date of completion of work as per original Agreement.	13.08.2012
7	Date of commencement of work/ Recording.	01-06-2013
8	Last Date of check measurement of work	11-07-2013

As per the above it is crystal clear that, the said Assistant engineer has executed the works of PYKAA building after the agreement period without valid permission, which should have been completed within (3) months from date of agreement.

Thus, Sri P.I. Praveen Kumar, AE, Jadcherla presently working in MPP Dhawada, Mahabubnagar district has failed to discharge his legitimate duties properly. Thus his action is in violation of Rule (3) of T.S.C.S. (Conduct) Rules, 1964.

Hence, the Charge.

**CHARGE-II :**

That Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district seignorage charges are not included in the Technical sanctioned Estimate and not recovered in bills of C/O PYKKA Building at Sarjakhanpet, Chennaram, Mirjapur, Chendravanha and Togapur, Villages.

**BASIS:**

The V&E Department made the following observations in their Vigilance Report No. 103 (298/V&E /E III/2017)/C.No.540/V&E/D2/2016), dt.27.10.2018 in respect of the works of C/O PYKKA Building at Sarjakhanpet, Chennaram, Mirjapur, Chendravanha and Togapur.

The Seignorage charges are not provided in the technical sanctions except in Mirjapur estimate but the payment was made to the above all works without deducting the seignorage charges in the M.Book. Due to which financial loss caused to Government.

(Contd.. on page..3)

::3::

Thus, Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district has failed to discharge his legitimate duties properly. Thus his action is in violation of Rule (3) of T.S.C.S. (Conduct) Rules, 1964.

Hence, the Charge.

**CHARGE-III:**

That Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district the excess payment was made to the Contractor for an amount of Rs.27,268/- by recording excess measurement.

**BASIS:**

The V&E Department made the following observations in their Vigilance Report No. 103 (298/V&E /E III/2017)/C.No.540/V&E/D2/2016), dt.27.10.2018 in respect of the all the (5) works:

**Work No.1:** In respect of C/O PYKKA Building at Sarjakhanpet location of the work is Sarjakhanpet (V), Kosgi (M) the recorded M.Book measurements are verified with respect to the field observation sheet and found not tallied with respect to the RR stone, Brick masonry & Plinth Beam. Impervious coat over Roof slab items were not executed but recorded and paid. An excess payment was made to the contractor for an amount of Rs.6,623/- towards the difference in measurements.

**Works No.2:** In respect of C/O PYKKA Building at Chennaram location of the work is Chennaram (V), Kosgi (M) the record M.Book measurements are verified with respect to the field observation sheet and were found not tallied with respect to the RR Stone, Brick Masonry, Plinth Beams and impervious coat on Roof Slab. An excess payment was made to the contractor for an amount of Rs.5,106/- towards the difference in measurements.

**Works No.3:** In respect of C/O PYKKA Building at Mirjapur location of the work is Mirjapur (V), Kosgi (M) the physical measurements of RR Stone, Brick Masonry & Flooring were verified and found not tallied with the recorded M.Book measurements. An excess payment was made to the contractor for an amount of Rs.1,985/- towards the difference in measurements.

**Works No.4:** In respect of C/O PYKKA Building at Chendravantha location of the work is Chendravantha (V), Kosgi (M) The physical measurements of CRS stone are verified and found not tallied with the M.Book recordings but fairly tallied for RCC Roof slab & Impervious coat with MB recordings. An excess payment was made to the contractor for an amount of Rs.5,050/- towards the difference in measurements.

**Works No.5:** In respect of C/O PYKKA Building at Togapur location of the work is Togapur (V), Kosgi (M) the physical measurements for items of RR Stone, Roof slab thickness are verified and found not tallied with M.Book recordings items of impervious coat is not executed in the site. An excess payment was made to the contractor for an amount of Rs.8,499/- towards the difference in measurements.

Which comes a total of Rs.6623+5106+1985+5050+8499=27,263/-

Thus, Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district has failed to discharge his legitimate duties properly. Thus his action is in violation of Rule (3) of T.S.C.S. (Conduct) Rules, 1964.

Hence, the Charge.

**CHARGE-IV:**

That Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district IT was not deducted for all the (5) works, FSD for work No.5 at Thogapur (V) were not deducted from the bill.

**(P.T.O)**

**::4::**

**BASIS:**

The V&E Department made certain observations in their Vigilance Report No. 103 (298/V&E /E III/2017)/C.No.540/V&E/D2/2016), dt.27.10.2018 in respect of the all the (5) works viz.,

**Work No.1:** C/O PYKKA Building at Sarjakhpet location of the work is Sarjakhpet (V), Kosgi (M).

**Works No.2:** C/O PYKKA Building at Chennaram location of the work is Chennaram (V), Kosgi (M).

**Works No.3:** C/O PYKKA Building at Mirjapur location of the work is Mirjapur (V), Kosgi (M).

**Works No.4:** C/O PYKKA Building at Chendravancha location of the work is Chendravancha (V), Kosgi (M).

**Works No.5:** C/O PYKKA Building at Togapur location of the work is Togapur (V), Kosgi (M).

In all the above (5) works Income tax was not deducted due to which financial loss caused to Government. The EMD & FSD for the work no.5 at Thogapur (v) were not deducted from the bill which loss caused to Governement.

Thus, Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district has failed to discharge his legitimate duties properly. Thus his action is in violation of Rule (3) of T.S.C.S. (Conduct) Rules, 1964.

Hence, the Charge.

**CHARGE-V :**

That Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district in C/o PYKKA Building at Mirjapur: Seigniorage charges are included in the Technical sanctioned Estimate, but same were not deducted in the bill.

**BASIS:**

The V&E Department made the following observations in their Vigilance Report No. 103 (298/V&E /E III/2017)/C.No.540/V&E/D2/2016), dt.27.10.2018 in respect of the work of C/O PYKKA Building at Mirjapur location of the work is Mirjapur (V), Kosgi (M).

The Seigniorage charges are provided in the estimate but the payment was made to the above work without deducting the seigniorage charges in the M.Book. Due to which financial loss caused to Government

Thus, Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district has failed to discharge his legitimate duties properly. Thus his action is in violation of Rule (3) of T.S.C.S. (Conduct) Rules, 1964.

Hence, the Charge. .

**CHARGE-VI :**

That Sri P.I.Praveen Kumar, AE Jadcherla presently working in MPP Dhawada, Mahabubnagar district in C/o PYKKA Building at Mirjapur: Shabad stone flooring area is sinking due to insufficient compaction below the flooring.

(Contd.. on page..5)

::5::

**BASIS:**

The V&E Department made the following observations in their Vigilance Report No. 103 (298/V&E /E III/2017)/C.No.540/V&E/D2/2016), dt.27.10.2018 in respect of the work of C/O PYKKA Building at Mirjapur location of the work is Mirjapur (V), Kosgi (M).

The Building has developed cracks along the wall joints and shabad stone flooring area sunk due to insufficient compaction below the flooring, which shown his negligence and slackness in performing official duties, due to which financial loss caused to Government.

Thus, Sri P.I.Praveen Kumar, AE, Jadcherla presently working in MPP Dhawada, Mahabubnagar district has failed to discharge his legitimate duties properly. Thus his action is in violation of Rule (3) of T.S.C.S. (Conduct) Rules, 1964.

Hence, the Charge. .

VIKAS RAJ  
PRINCIPAL SECRETARY TO GOVERNMENT (PR&RD)

SECTION OFFICER

**ANNEXURE –II**

(Annexure to G.O.Rt.No.499, PR&RD (Vig.I) Dept., dt.29.08.2019)

**LIST OF THE DOCUMENTS BY WHICH THE ARTICLE OF CHARGES FRAMED AGAINST SRI P.I. PRAVEEN KUMAR, ASSISTANT ENGINEER, JADCHERLA PRESENTLY WORKING IN MPP DHAWADA, MAHABUBNAGAR DISTRICT ARE PROPOSED TO BE SUSTAINED.**

Vigilance Report No. 103 (298/V&E /E III/2017)/C.No.540/V&E/D2/2016), dt.27.10.2018

VIKAS RAJ  
PRINCIPAL SECRETARY TO GOVERNMENT (PR&RD)

SECTION OFFICER

**ANNEXURE – III**

(Annexure to G.O.Rt.No.499, PR&RD (Vig.I) Dept., dt.29.08.2019)

**LIST OF WITNESSES BY WHOM THE ARTICLE OF CHARGES FRAMED SRI P.I. PRAVEEN KUMAR, ASSISTANT ENGINEER, JADCHERLA PRESENTLY WORKING IN MPP DHAWADA, MAHABUBNAGAR DISTRICT ARE PROPOSED TO BE SUSTAINED.**

-NIL-

VIKAS RAJ  
PRINCIPAL SECRETARY TO GOVERNMENT (PR&RD)

SECTION OFFICER